


## BUILDING SAFETY CERTIFICATE


Certified that the existing building D. Y. Patil Dnyanshanti School, Akudi at Dr D. Y. Patil Pratishthan Educational Complex, Sector 29, Akurdi, Pune 411044 comprised of B+G+4 occupied by D. Y. Patil Dnyanshanti School, Akudi at Dr D. Y. Patil Pratishthan Educational Complex, Sector 29, Akurdi, Pune 411044 have complied with the Building safety requirements and verified by the officers concerned of Public Works Department on 27.06.2023 in the presence of Principal, D. Y. Patil Dnyanshanti School, Akudi at Dr D. Y. Patil Pratishthan Educational Complex, Sector 29, Akurdi, Pune 411044 and that the building is structurally safe based on the structural stability certificate attached in the proposal and fit for occupancy with effect from 27.06.2023 for a period of 1 years.

Issued on 27/06/2023 at Pune by

  
(V. M. Kulthe)  
Sub Divisional Engineer  
P. W. Sub Division No 5,  
Pune 411001. ✍

No. DB/Building Safety Certificate/4867/2023  
Office OF the Executive Engineer,  
P.W. Division, Pune-1  
Dated :- 27 JUN 2023



'Countersigned'  
  
(Dr. S.-R. Katkar)  
Executive Engineer  
Public Works Division,  
Pune-411 001.

- Copy to:-
1. D. Y. Patil Dnyanshanti School, Akudi at Dr D. Y. Patil Pratishthan Educational Complex, Sector 29, Akurdi, Pune 411044
  2. Sub Divisional Engineer, P. W. Sub Division No 5, Pune 411001

For Dr. D.Y. Patil Pratishthan

  
Authorised Signatory

  
**PRINCIPAL**  
D. Y. Patil Dnyanshanti School  
Sec. No.29, Akurdi, Ravet,  
Pune 41